Edgardo Gomez

PO BOX 1392 Temecula, CA 92593 714-349-7120

United State Bankruptcy Court For the District of Oregon

Judge McKittrick Case #23-62260-dwh-11 ECF No 243 Claim No. 248

Honorable Judge McKittrick

Thank you for being part of this mediation process, rest assure that I will continue to be patient and understanding of VANS AIRCRAFT situation, as I have been since the beginning of my dealings with this company in 2021. In addition, I am willing to work collaboratively with the other party to find a reasonable solution.

We have reached this point-in-the bankruptcy proceedings due to the objection to my claim in which the other party stated:

- I- That I had agreed to a change on the price of my aircraft kit.
- 2- Laser cut parts have been tested and found safe.
- 3- My claim is inconsistent with debtor's books and records.

During this process I have not had the opportunity to respond to those objections and clarify why those statements are not consistent with reality; I hope to do so during our conference.

In this folder I have attached five documents with supporting documentation from various sources, including VANS AIRCRAFT as well as a video link to a proposed repair/solution to a laser cut part. Also, I intend to rely on my 34 years of experience in the aircraft industry as well as an informed consumer.

Thank you

Edgardo Gomez

Mr. Gomez,

As we had previously discussed, Van's has now prepared a repair video for you. You can view the video at this link, but it is unique to you so I believe you will need to link though your email account: https://youtu.be/65PDi4Qff3k Once you have watched the video, you can then set up a call with Brian Hickman, a Van's engineer, to review and discuss any other questions you may have as to how to complete the repairs. Mr. Hickman is copied on this email. Once you have completed that process, we can then discuss any further questions you may have with respect to your claim.

Thanks,

Tim

Timothy J. Conway | Tonkon Torp LLP

Partner 888 SW Fifth Ave., Suite 1600 Portland OR 97204 503.802.2027 direct tim.conway@tonkon.com | website | bio

This message may contain confidential and privileged communications and privileged information. If you received this message in error, please delete it and notify me promptly.

Update on your Van's order!

kıtstatus@vansaircraft com <kıtstatus@vansaircraft com> Tue 8/29/2023 3 09 PM To edgo2@msn com <edgo2@msn com>



Dear Van's Customer,

We have an update to share related to your Van's Aircraft kit order. Items that have changed are marked below in orange

Order #223286

Item RV-8 FINISH KIT

Status Assigned to Crating

Crating Sep 5 2023 - Oct 28 2023 (estimated)

Reason I fold up due to engine mount

You are receiving this email order update because you have an active kit order with Van's Aircraft. We send these updates when the status changes on one or more items on your orders, to keep you informed of your order status.

> Contact us at kitstalus@vansairciaft.com 14401 Keil Road NE, Aurora, 503-678-6545

Re. Van's Final Payment Request 223286

ed gomez <edgo2@msn com>

Fri 2/17/2023 5 14 AM

To Kit Status <kitstatus@vansairciaft com>

Hello, the shipping address for this kit is; FRENCH VALLEY AIRPORT BLDG. 82, HANGAR 25. 37840 SKY CANYON DR.

MURRIETA, CA. 92563.

Be advised that the shipper will need to call me before delivery so I can let them into the airport

Thank you Ed

From: Kit Status < kitstatus@vansaircraft com> Sent: Wednesday, February 15, 2023 10 17 PM To: edgo2@msn com <edgo2@msn com> Subject: Van's Final Payment Request 223286

Hello,

It's almost time to start packing your kit! To do so, we need to collect your balance due of \$7,096 94 Please refer to the attached order acknowledgement

Important: Please confirm the below shipping address is correct before sending payment If a change is required, please reply to this email

33217 CALLE LANGARICA

TEMECULA. CA 92592 UNITED STATES

This is your final opportunity to make changes to your order. Changes must be completed prior to receiving your final payment. After we receive final payment we will add your kit to the schedule and will no longer accept changes.

You may pay by wire transfer, check, or with a credit/debit card on our secure payment portal at vansaircraft com/makeapayment/ We cannot take payment over the phone Once we receive and process your payment, we will send an email confirming receipt

If you have a will-call order, we will schedule your pick-up date and communicate with you when the order is ready

You can keep track of the status of your kit at vansaircraft.com/kitstatus/ Thank you,



Aric Krause

Kit Logistics, Van's Aircraft, Inc. (503)678-6545 office | aric@vansaircraft.com

www vansaircraft com

14401 Keil Rd NE, Aurora Orogon 97002

This email message is for the sole use of the intended recipient(s) and may contain confidential and privileged information. Any unauthorized review, use, disclosure or distribution is prohibited If you are not the intended recipient, please contact the sender by reply email and destroy all copies of the original message. If you are the intended recipient, please be advised that the content of this message is subject to access, review and disclosure by the sender's Email System Administrator

	(c	Q Search
	Home View Help	
	` , ,) [jj] Delete ∨	☐ Archive '(open) with the Move to ∨ ← Reply ∨ (↓
00	∨ Folders	$ imes$ Close Previous Next $ ilde{\mathcal{O}}$ 2 ${}_{\!$
	☑ Inbox 369	BUILDER # 83962
\$	Co Junk Email 3	ed gomez
Mā	₹ Diafts 1	To Kit Sales Wed 11/2/2022 4 57 PM
	Sent Items	إ _{ديا}
圈,:	Deleted It . 413	2 attachments (176 KB) △ Save all to OneDrive 😾 Dovrhoad all
	☐ Archive	
(gg)		HI, i like to order a finishing kit for anRV-8. Attached is the ordering form I may be getting the engine from other source
,, 3	CAP	Also, I will be making a deposit with my credit card for \$2000 Any question please let me know.
	Conversation	Thanks, ed
	Create new fold	Cu
	∨ Groups	← Reply → Forward

New group

♥ Upgrade to Microsoft 365 with premium Outlook features



VANS AIRCRAFT, INC.

Order Acknowledgement

223286

14401 N.E. KEIL RD. AURORA, OR 97002

Customer:

83962

GOMEZ, EDGARDO

PO BOX 1392

TEMECULA, CA 92593

UNITED STATES

Telephone:

714-349-7120

Email:

edgo2@msn.com

Shipping address:

GOMEZ, EDGARDO

33217 CALLE LANGARICA

TEMECULA, CA 92592

UNITED STATES

Shipping Instructions:

TRUCK

Ì	Sales Order	Order Date	Order Terms	Salesperson	Purchase Order
Ì	223286	11/02/22	NET B4 DEL	Jake	FIN

Stock code	Description	Bin_	Order quantity	Unit price	Gross amount
RV-8 FINISH KIT	KIT==============		1	8,300.00	8,300.00
8 FIN COWL KIT-IO	COWL KIT W/O SCOOP		1	0.00	0.00
WD-801-D1-PC	DYNA 1 ENG.MNT. *	F2A	1	0.00	0.00
DELETE SPINNER			1-	120.00	120,00-
CRATING CHARGE			1	185.00	185.00

----- Deposit Receipt -----

Deposit amount :

2000,00

Paid as: WEB CREDIT CARD PAYMENTS



RV-8/8A SPECIAL FINISHING KIT ORDER FORM Use when installing engines not supplied by Van's

Coo When meta	annig engines <u>not</u> s	аррпос	a by vai			8-26-22		
- RICA TEMECULA C Day phone 714 - 349	392 A. 92593 17 CAIIE LANGA-	1 Kit 2 A 2 3 Cus 4 Kits 5 \$50 6 Pay Mas 7 Kit 8. Pric 9 Free carr 10 Van the 11 Sigi of L	prices are prices from prices are prices are prices are prices are prices are prices are ex-work and a return Varusbility Agreer exe are subject	es in effeust accomed delays in full befordable if funds chever nust be in ks Aurora re prepai cannot a 's Aircraftent,	d or collect, deper assist in certifying t standard Waiver ge without notice	ce increases hipped or Visa/ ail or FAX) nding on kits out-side		
FINISHING KIT		······		RV-8	\$8,300.00	(
				RV-8A	\$9,600.00			
Crating Charge			Re	gular_\$1	85 00			
If you are using a new Lycoming from Van's use to Van's engine mounts and cowls fit the engines we Lycoming models To provide us the information we need, you must engine. Without this information we cannot accept figure are installing an engine that is not compatibe the credit will be determined by Van's It is the customer's responsibility to provide accurated.	e sell Other engine suppliers produ- complete the ENGINE INDENTIFIC, it your order lie with Lycoming style mounts or co	you are usin ce a wide va ATION form wl, you may	riety of engine on the reverse delete these if	s that ma by circlir ems for c	ny or may not corre	espond to lescribe your amount of		
ENGINE MOUNT	Use data sheet on opposite s	ide		None				
COWL TYPE	Use data sheet on opposite s	ide		None				
SPINNER TYPE NOTE if supplying own spinner buying new MT prop (supplied with spinner) –seld none	or Hartzell Se ect constant-speed fix	ensenich ed-pitch	Wood fixed-pitch	\$	None 120 00 credit			
TOTAL CRATING CHARGE (If using fillab	le form leave blank)							
TOTAL ORDER (If using fillable form leave blank)								
METHOD OF PAYMENT (If credit card, pay through Van's website) CREDIT CARD								
AMOUNT ENCLOSED (25% minimum de	AMOUNT ENCLOSED (25% minimum deposit required)							
Customer Number of Previously Completed/Flown RV: 83 962								

E-Mail to: kits@vansaircraft.com

Update on your Van's order!

kitstatus@vansaircraft.com < kitstatus@vansaircraft.com >

Tue 11/8/2022 10 45 PM

To. edgo2@msn com <edgo2@msn com>



Dear Van's Customer,

We have an update to share related to your Van's Aircraft kit order. Items that have changed are marked below in orange.

Order #223286

Item RV 81 INGHEIT (new)
Status. Parts Being Produced

You are receiving this email order update because you have an active kit order with Van's Aircraft. We send these updates when the status changes on one or more items on your orders, to keep you informed of your order status.

Contact us at kitstatus@vansaircraft com 14401 Keil Road NE, Aurora, 503-678-6545 Case 23-62260-dwh11 Doc 742 Filed 01/10/25 //-2-22

Thanks for submitting your payment If you provided an email address, please check your email account for a transaction receipt from our payment processor, Authorize.net.

Print or save a copy of this page for your records. The information shown below has been submitted to Van's Aircraft.

What is the purpose of this payment?

25% deposit on a kit

Kıt serial number

83962

Notes

this is a deposit for a finishing kit for an RV-8 the finishing kit order form has been emailed to you on 11/2/22 and the engine I will be using is the YIO360-M1B

Your Name

edgardo gomez

Email

odoo wan n com

Phone

(714) 349-7120

Credit Card Billing Address

po box 1392

Physi y - Term

Transaction Receipt from Vans Aircraft Inc for \$2000.00 (USD)

Auto-Receipt <noreply@mail.authorize.net>

Wed 11/2/2022 5 04 PM

To EDGARDO GOMEZ <edgo2@msn.com>

Description

Make a Secure Payment

Invoice Number 6362a3108c659

Billing Information

Shipping Information

EDGARDO GOMEZ po box 1392 Temecula, CA 92593 **United States** edgo2@msn com (714) 349-7120

Item Name

Description Qty Taxable

Unit Price

Item Total

Amount to authorize and charge

Υ 1

\$2000.00 (USD) \$2000 00 (USD)

Total: \$2000.00 (USD)

Date/Time.

2-Nov-2022 10 04 16 PDT

Transaction ID

64027760963

Payment Method.

Visa xxxx3792

Transaction Type:

Purchase

Auth Code

02535D

Vans Aircraft Inc Aurora, OR 97002 US spete@vansaircraft com



VAN'S AIRCRAFT

VANS AIRCRAFT, INC.

Order Acknowledgement

14401 N.E. KEIL RD. AURORA, OR 97002 223286

83962

O CONTRACTOR OF THE CONTRACTOR

* 223286*

Customer.

83962

GOMEZ, EDGARDO

PO BOX 1392

TEMECULA, CA 92593

UNITED STATES

Telephone:

714-349-7120

Email:

edgo2@msn.com

Shipping address:

GOMEZ, EDGARDO

33217 CALLE LANGARICA

TEMECULA, CA 92592

UNITED STATES

Shipping Instructions

TRUCK

Sales Order Order Date Order Terms		Balance	Salesperson	Purchase Order		
Γ	223286	11/02/22	NET B4 DEL	7,096 94	Jake	FIN

Stock code	Description	Bın	Order quantity	Unit price	Gross amount
RV-8 FINISH KIT	KIT=============		1	8,300.00	8,300.00
8 FIN COWL KIT-IO	COWL KIT W/O SCOOP		1	0.00	0 00
WD-801-D1-PC	DYNA 1 ENG.MNT *	F2A	1	0 00	0 00
DELETE SPINNER			1-	120 00	120 00-
CRATING CHARGE			1	185.00	185.00

----- Deposit Receipt -----

Deposit amount

2000 00

Paid as WEB CREDIT CARD PAYMENTS

Page 1 of 2

final PAYMENT FOR FINISH KIT 2-16-23

Thanks for submitting your payment If you provided an email address, please check your email account for a transaction receipt from our payment processor, Authorize net

Print or save a copy of this page for your records. The information shown below has been submitted to Van's Aircraft.

What is the purpose of this payment?

Balance payment on a kit

Order/Statment Number

223286

Kıt serial number

83962

Notes

This is the final payment for RV 8 finish kit

Your Name

edgardo gomez

Email

top office it

Phone

(714) 349-7120

Credit Card Billing Address

Transaction Receipt from Vans Aircraft Inc for \$7096.94 (USD)

Auto-Receipt <noreply@mail authorize.net>

Fii 2/17/2023 5 19 AM

To EDGARDO GOMEZ <edgo2@msn com>

Description

Make a Secure Payment

Invoice Number 63ef0e4b7e025

Billing Information

Shipping Information

EDGARDO GOMEZ po box 1392 Temecula, CA 92593 **United States** edgo2@msn com (714) 349-7120

Item Name

Description Qty Taxable

Unit Price

Item Total

Amount to authorize and charge

\$7096 94 (USD) \$7096 94 (USD)

Total: \$7096.94 (USD)

Date/Time

16-Feb-2023 21 19 07 PST

Transaction ID

64208928156

Payment Method

Vısa xxxx3792

Transaction Type

Purchase

Auth Code

07263D

Vans Aircraft Inc Aurora, OR 97002 US spete@vansaircraft com

My Orders

Case 23-62260-dwh11 Doc 742 Filed 01/10/25

Master Acct Number M015451

Below is a list of your previous bit orders to review. If you wish to modify your order and accept the new terms and conditions, please click the Reorder' button on that order's line to add that item to your cart. Once you have selected the order(s) you want to modify and reorder, click the Review Orders" button. You will be shown the list of orders to confirm. Once confirmed, you can submit your order and we will send you an agreement via DocuSign for your signature. No additional deposits or phyments are required to submit your order modification

Account

Company

GOMEZ, EDGARDO

Name

GOMEZ, EDGARDO

Email

edgo2@msn com

Original Orders

Original Total

\$9,096 94

Original Deposit

\$9,096 94

Click "Reorder" to select the order(s) from the list below that you wish to modify and reorder under the new price/terms If you do not want to modify and reorder an item, you do not need to take any action on those items

Senal Number Original Price Deposit New Price Increase Origina Order Number Order Type Received \$4,746 94 223286 RV-8 FINISH KIT 83962 \$9,096 94 \$9,096 94 \$13,843 88

> If you see any discrepancies with your order(s) from this list, please send us a question with the specific order number and a description of the issue so we can

> > Items in Cart 0 Cart Total \$000

Original Deposit \$000

Remaining Balance \$000

REORDERED ON 1-19-24

Case 23-62260-dwh11 Doc 742 Filed 01/10/25

Orders updated. You're all set!

Review Orders - Creating Document - Submitting for Signing - Completed

Please check your inbox for email(s) to complete the e-signatures required to update your contracts and complete your modified order(s)



VANS AIRCRAFT, INC

14401 N E KEIL RD AURORA, OR 97002 Invoice

320909

Purchase Order

FIN





Customer 83962

> GOMEZ, EDGARDO PO BOX 1392

TEMECULA, CA 92593

US

Telephone. 714 349 7120

Sales Order

Email.

223286

edgo2@msn com

Invoice Date

05/24/24

Shipping address

GOMEZ, EDGARDO

FRENCH VALLEY AIRPORT BLDG.

82 HANGAR 25

37840 SKY CANYON DR

MURRIETA

CA

UNITED STATES

92563

Shipping Instructions.

ABF 145166472

Salesperson

Jake

Tracking Number:

Order Terms

PAID

macking manus		

ELOZOO	337.1.2.			
Stock code	Description	Ship quantity	Unit price	Gross amount
RV-8 FINISH KIT	=== STANDARDIZED KIT =============	1	12,850 00	12,850,00
AIRFRAME KIT 50% CAP	PRICE ADJUSTMENT	1-	400.00	400 00-
8 FIN COWL KIT-IO	COWL KIT W/O SCOOP	1	0 00	0 00
WD-801-D1-PC	DYNA 1 ENG MNT. *	1	0 00	0.00
DELETE SPINNER		1-	129 00	120 00-

Order Date

11/02/22

----- Payment Method -----

DEPOSIT

13408 88

Total payment

13408 88

invoice amount Change given

13408 88 0 00

NOTES

Total gross. 12,330.00 Total discount: 0.00 1,078.88 Total tax

Total freight.

0.00

Less Payment

13,408.88

Net amount due:

0.00

CURRENCY USD



14401 Keil Road NE, Aurora, Oregon, USA 97002
PHONE 503-678-6545 • FAX 503-678-6560
www vansaircraft com • info@vansaircraft com

Congratulations on the shipment of your kit!

Obviously, we want your kit to arrive safely and in one piece; however, sometimes, damage occurs during shipping. It is <u>extremely important</u> that you catch these things upon delivery! Here are the top tips for receiving your kit.

First, carefully examine your crate upon arrival. Look for any outside damage (including the bottom of the crate). **Note the damage to your copy of the Bill of Lading before you sign. Take photos of the exterior damage as it is being unloaded, from all angles.**

Make sure you visually confirm that the driver has noted the crate as damaged on their copy of the paperwork or on their handheld device. Sometimes, drivers will claim they are unable to mark a shipment as damaged, this is untrue. Never accept the driver's word that they will note the damage on their end later.

Second, it is important to know that our crates are very well made, and even if the crate looks destroyed, a lot of the time, the actual parts inside are safe.

***VERY IMPORTANT: You must keep the damaged items in your possession for 30 days in case the freight company would like to inspect your items.

You are responsible for making the claim with the freight company. You can order the damaged parts from Van's Aircraft, Inc. and Van's Aircraft, Inc. will charge/ship you the parts that are needed. Once you have the invoice/receipt from Van's Aircraft, Inc. on what you paid for the parts plus shipping, you can use this for your damage claim with the freight company.

Freight companies will need pics of crate/parts that are damaged with a copy of packing list, bill of lading, and invoice.

Please contact <u>jamilyn@vansaircraft.com</u> if you have any freight damage questions.



14401 Keil Road NE, Aurora, Oregon, USA 97002
PHONE 503-678-6545 • FAX 503-678-6560
www.vansaircraft.com • Info@vansaircraft.com

Dear RV Builder: You are receiving this because your kit is in the process of being shipped!

We have shipped your kit or parts using the freight company which had the best rates for your shipment, and they will email you your Bill of Lading with your tracking number. The freight company has been instructed by Van's Aircraft to call you prior to delivery to set up a day and time for delivery and/or pickup from their terminal.

Freight can be shipped collect or prepaid, depending on the transport company. If this is a collect shipment (noted as COD) on your Bill of Lading, you will pay the freight company upon delivery. If the charges are prepaid, either your credit card will or has been billed, or you will be invoiced on a net 30 basis for the freight costs. *Note: Prepaid shipments might cost more due to Van's Aircraft, Inc additional processing fees.

IMPORTANT:

Contained in your crate is a packing list which details all parts included in the kit. The items marked **B/O** were out of stock at the time of shipment and will be forwarded to you as soon as possible. Upon delivery of your kit, **you are given 30 days in which to inventory.** We do not accept responsibility for shortages reported **more** than 30 days after receipt of the kit.

Within this timeframe, if you find shortages other than those noted as b/o, please contact orders@vansaircraft.com or call the parts department, 503 678 6545 option 1.

If you have to re-order parts for whatever reason, please use the part numbers that were provided on the packing list sent with the kit. We are always making changes in inventory, and there could be several styles of the part to choose from. Note the quantity as indicated on the list and determine how much/many you need before you call in your order. We cannot accept orders such as "enough angle to re-do the elevator," "all the parts for an aileron," or "ask one of the tech support memberts to figure it out." All the information you need to formulate your order is available to you, either on the packing list or on our webstore.

Support is available to answer your building questions by phone from 7:30 to 9:30 AM, and 3:00 to 4:00 PM PST, Monday thru Friday, and all day by emailing support@vansaircraft.com

TRUCKING COMPANY PHONE NUMBERS:

ABF FREIGHT:	1-800-367-2237	FEDEX FREIGHT	1-800-845-4647
XPO LOGISTICS	1-800-755-2728	OIA GLOBAL	1-855-642-3973
STEWART TRANSPORT	1-602-283-2777	GEO S BUSH	1-503-228-6501
OLD DOMINION.	1-866-905-6335	SAIA [,]	1-800-765-7242
LYNDEN INTL:	1-503-257-8870	UPS:	1-206-288-2940

Van's Aircraft Contact Emails

kits@vansaircraft com

Airframe kit/contract purchase agreements including EMP / WING / FUSE / FIN / QB / ENGINE / PROP

kıtstatus@vansalıcıaft coni

Status of the kits

orders@vansairciaft com

Inventory discrepancies, backorders, parts/accessory orders you cannot complete via the web store https://store-vansaucraft.com/

support@vansaircraft com

Tech Support guidance should you encounter build difficulty.

registrations@vansalicraft.com

Transfer of ownership & Bill of Sale upon completion of your RV

<u>ramılyn@vansaircraft com</u>

International/Domestic Freight inquiries/Damage Freight claims



VANS AIRCRAFT, INC.

Order Acknowledgement

14401 N.E. KEIL RD. AURORA, OR 97002 223286

* 83962*

* 223286*

Customer:

83962

GOMEZ, EDGARDO

PO BOX 1392

TEMECULA, CA 92593

US

Telephone:

714 349 7120

Email:

edgo2@msn com

Shipping address:

GOMEZ, EDGARDO

FRENCH VALLEY AIRPORT BLDG. 82

HANGAR 25

37840 SKY CANYON DR MURRIETA, CA 92563

UNITED STATES

Shipping Instructions

TRUCK

	Sales Order Order Date Order Terms		Balance	Salesperson	Purchase Order	
I	223286	11/02/22	NET B4 DEL	4,311 94	Jake	FIN

Stock code	Description	Bin	Order quantity	Unit price	Gross amount
RV-8 FINISH KIT	=== STANDARDIZED KIT ======		1	12,850.00	12,850.00
AIRFRAME KIT 50% CAP	PRICE ADJUSTMENT		1-	400.00	400.00-
8 FIN COWL KIT-IO	COWL KIT W/O SCOOP		1	0.00	0.00
WD-801-D1-PC	DYNA 1 ENG.MNT. *	F2A	1	0.00	0.00
DELETE SPINNER			1-	120.00	120.00-

----- Deposit Receipt -----

Deposit amount

7096 94

Paid as WEB CREDIT CARD PAYMENTS

Total deposit

9096 94

Thanks for submitting your payment If you provided an email address, please check your email account for a transaction receipt from our payment processor, Authorize net

Print or save a copy of this page for your records. The information shown below has been submitted to Van's Aircraft.

What is the purpose of this payment?

Balance payment on a kit

Order/Statment Number

223286

Kıt serial number

83962

Notes

final payment for finishing kit

Your Name

EDGARDO GOMEZ

Email

dog 26 day ii com

Phone

(714) 349-7120

Credit Card Billing Address

PO BOX 1392 TEMECULA, California 92593 United States Map It

Credit Card

- 11 1105

PAYMENT RECEIVED: EDGARDO GOMEZ \$4,311.94

Hughes, Greg (Kit Sales) < kits@vansaircraft com>

Fii 5/17/2024 5 36 PM

To GOMEZ, EDGARDO <edgo2@msn com>

WEB PAYMENT RECEIVED

What is the purpose of this payment?

Balance payment on a kit

Order/Statment Number

223286

Kit serial number

83962

Notes

final payment for finishing kit

Your Name

EDGARDO GOMEZ

Email

edgo2@msn.com

Phone

(714) 349-7120

Credit Card Billing Address

PO. BOX 1392 TEMECULA, California 92593 United States Map It

Credit Card

Visa

XXXXXXXXXXXI760

Order

Product	Qtγ	Unit Price		Price
Amount to authorize and charge:	1	\$4,311.94		\$4,311.94
			Sub Total	\$4,311.94
			Total	\$4,311.94

This email message is for the sole use of the intended recipient(s) and may contain confidential and privileged information. Any unauthorized review use, disclosure or distribution is prohibited. If you are not the intended recipient, please contact the sender by reply email and destroy all copies of the original message. If you are the intended recipient, please be advised that the content of this inessage is subject to access, review and disclosure by the sender's Email by saint numbers own

This email is a service from Van's Aucraft Delivered by Zendesk

Transaction Receipt from Vans Aircraft Inc for \$4311.94 (USD)

Auto-Receipt <noreply@mail.authorize net>

Fri 5/17/2024 5 36 PM

To edgardo gomez <edgo2@msn com>

Description

Make a Secure Payment

Invoice Number 664795978e735

Billing Information

Shipping Information

edgardo gomez TO BOX 1092 TEMECULA, California 92593 United States

edgo2@msn com (714) 349-7120

Item Name

Description Qty Taxable

Unit Price

Item Total

Amount to authorize and charge

Υ 1

\$4311.94 (USD) \$4311 94 (USD)

Total: \$4311.94 (USD)

Date/Time

17-May-2024 10 36 23 PDT

Transaction ID

120441783973

Payment Method

Visa xxxx1760

Transaction Type

Purchase

Auth Code

08734D

Vans Aircraft Inc Aurora, OR 97002

US

greg@vansaircraft com



VANS AIRCRAFT, INC.

Deposit Receipt

14401 N.E. KEIL RD. AURORA, OR 97002 320167

Customer

83962

GOMEZ, EDGARDO PO BOX 1392

TEMECULA, CA 92593

US

Telephone: 714 349 7120

Email

edgo2@msn com

Shipping address:

GOMEZ, EDGARDO

FRENCH VALLEY AIRPORT BLDG.

82 HANGAR 25

37840 SKY CANYON DR

MURRIETA

CA

UNITED STATES

92563

Shipping Instructions.

TRUCK

Tracking Number:

Sales Order	Involce Date	Order Date	Salesperson	Purchase Order
223286	05/17/24	11/02/22	Jake	FIN

Warehouse Ship quantity Unit price Gross amount Description Stock code

---- Deposit Receipt -----

Deposit amount

4311 94

Paid as WEB CREDIT CARD PAYMENTS

Total deposit

13408 88

NOTES




Figure 4-97. Rivet defects.

holes show elongation, replace the rivets with the next larger size. Sheet failures such as tear-outs, cracks between rivets, and the like usually indicate damaged rivets. The complete repair of the joint may require replacement of the rivets with the next larger size.

The general practice of replacing a rivet with the next larger size (1/32-inch greater diameter) is necessary to obtain the proper joint strength of rivet and sheet when the original rivet hole is enlarged. If the rivet in an elongated hole is replaced by a rivet of the same size, its ability to carry its share of the shear load is impaired and joint weakness results.

Removal of Rivets

When a rivet has to be replaced, remove it carefully to retain the rivet hole's original size and shape. If removed correctly, the rivet does not need to be replaced with one of the next larger size. Also, if the rivet is not removed properly, the strength of the joint may be weakened and the replacement of rivets made more difficult.

When removing a rivet, work on the manufactured head. It is more symmetrical about the shank than the shop head, and there is less chance of damaging the rivet hole or the material

around it. To remove rivets, use hand tools, a power drill, or a combination of both.

The procedure for universal or protruding head rivet removal is as follows:

1. File a flat area on the head of the rivet and center punch the flat surface for drilling.

Note: On thin metal, back up the rivet on the upset head when center punching to avoid depressing the metal.

2. Use a drill bit one size smaller than the rivet shank to drill out the rivet head.

Note: When using a power drill, set the drill on the rivet and rotate the chuck several revolutions by hand before turning on the power. This procedure helps the drill cut a good starting spot and eliminates the chance of the drill slipping off and tracking across the metal.

3. Drill the rivet to the depth of its head, while holding the drill at a 90° angle. Do not drill too deeply, as the rivet shank will then turn with the drill and tear the surrounding metal.

Note: The rivet head often breaks away and climbs

if an excessively small rivet diameter is selected for thick material, the shear strength of the rivet is not great enough to carry the load of the joint. As a general rule, the rivet diameter should be at least two and a half to three times the thickness of the thicker sheet. Rivets most commonly chosen in the assembly and repair of aircraft range from 3/32-inch to 3/4-inch in diameter. Ordinarily, rivets smaller than 3/42-inch in diameter are never used on any structural parts that carry stresses.

The proper sized rivets to use for any repair can also be determined by referring to the rivets (used by the manufacturer) in the next parallel row inboard on the wing or forward on the fuselage. Another method of determining the size of rivets to be used is to multiply the skin's thickness by 3 and use the next larger size rivet corresponding to that figure. For example, if the skin is 0.040 inch thick, multiply 0.040 inch by 3 to get 0.120 inch and use the next larger size of rivet, 1/2-inch (0.125 inch).

When rivets are to pass completely through tubular members, select a rivet diameter equivalent to at least ½ the outside diameter of the tube. If one tube sleeves or fits over another, take the outside diameter of the outside tube and use one-eighth of that distance as the minimum rivet diameter. A good practice is to calculate the minimum rivet diameter and then use the next larger size rivet.

Whenever possible, select rivets of the same alloy number as the material being riveted. For example, use 1100 and 3003 rivets on parts fabricated from 1100 and 3003 alloys, and 2117-1 and 2017-T rivets on parts fabricated from 2017 and 2024 alloys.

The size of the formed head is the visual standard of a proper rivet installation. The minimum and maximum sizes, as well as the ideal size, are shown in *Figure 4-76*.

Installation of Rivets

Repair Layout

Repair layout involves determining the number of rivets required, the proper size and style of rivets to be used, their material, temper condition and strength, the size of the holes, the distances between the holes, and the distance between the holes and the edges of the patch. Distances are measured in terms of rivet diameter.

Rivet Length

To determine the total length of a rivet to be installed, the combined thickness of the materials to be joined must first be known. This measurement is known as the grip length. The total length of the rivet equals the grip length plus the amount of rivet shank needed to form a proper shop head.

The properly formed shop head equals one and a half times the diameter of the rivet shank. Where A is total rivet length, B is grip length, and C is the length of the material needed to form a shop head, this formula can be represented as A = B + C. [Figure 4-76]

Rivet Strength

For structural applications, the strength of the replacement rivets is of primary importance. [Figure 4-77] Replace rivets with those of the same size and strength whenever possible. If the rivet hole becomes enlarged, deformed, or otherwise damaged; drill or ream the hole for the next larger size rivet. However, make sure that the edge distance and spacing is not less than minimums listed in the next paragraph. Rivets may not be replaced by a type having lower strength properties, unless the lower strength is adequately compensated by an increase in size or a greater number of rivets. For example, it is acceptable to replace 2017 rivets of 3/16 inch diameter or less, and 2024 rivets of 5/32 inch diameter or less with 2117 rivets for general repairs, provided the replacement rivets are 1/32 inch greater in diameter than the rivets they replace.

The 2117-T rivet is used for general repair work, since it requires no heat treatment, is fairly soft and strong, and is highly corrosion resistant when used with most types of alloys. Always consult the maintenance manual for correct rivet type and material. The type of rivet head to select for a particular repair job can be determined by referring to the





Figure 4-76, Rivet formed head dimensions.

Case 23-62260-dwh11 Doc 742 Filed 01/10/25





jack202020 I'm New Here

jack202020 said:

RV-10 Empennage for sale.

Tailcone mostly complete. Horizontal and Vertical Stabilizers complete. All Van's recommended LCP parts are in hand. No parts replaced. 183 hours, all steps logged.

Reply

#2

Stopped with LCP and Vans Bankruptcy. Ended up buying into a Cherokee Six during that time. Asking \$7000 OBO. Warsaw Indiana.

I also have tools (DDRT2, manual squeezer, dies, rivet gun, tungsten bucking bar), and am willing to sell with the tail, not separate, for an additional price.

Home Forum



Support the definitive community for RV builders and enthusiasts — upgrade your account today!

View upgrades

You get a badge showing your support and some tiers unlock additional features, ad-free viewing, and access to an exclusive forum.

Home Forums Main Classifieds

RV-12iS Wing, Empennage, and Fastener kits for sale

△ JP4 · ⑤ Nov 20, 2024









Jump to new \

Watch

Nov 20, 2024

#1

The second of th

I bought a flying airplane, so I'm looking to sell these RV-12iS kits.

Wing kit with dual landing lights, no LCP, not started.

Empennage kit, barely started, has some LCP, but all required parts replaced. Full fastener kit.

JP4 Member

Patron

Kits are inventoried and still crated. \$8,995 local pickup or I can assist in delivery within a few hours of Hood River, OR. Vans current pricing before crating \$20,525

Home Forum '



Support the definitive community for RV builders and enthusiasts — upgrade your account today!

View upgrades

You get a badge showing your support and some tiers unlock additional features, ad-free viewing, and access to an exclusive forum.

Home

Forums

Main

Classifieds

2024 RV8 For Sale, Un painted 80 Hrs TT. \$195,000

A YellaDawg · O Nov 28, 2024









Jump to new

Watch

#1

YellaDawg Well Known Member

Sponsor

Nov 28, 2024

QuickBuild with all Showplanes' Mods: Fastback, Tip Over Canopy, extended cowl. Pre LCP and Primer Wash issues.

- -Lycoming IO390 EXP 119 215HP
- -Dual PMags
- -Vetterman exhaust
- -13 row oil cooler with Showplanes mount
- -Hartzell aerobatic aluminum 74" Constant Speed prop

Home Forum



Support the definitive community for RV builders and enthusiasts — upgrade your account today!

View upgrades

You get a badge showing your support and some tiers unlock additional features, ad-free viewing, and access to an exclusive forum.

Classifieds

RV-14A Empennage and Wing - price reduced

⇔ ericp · ○ Nov 9, 2024







Completed RV14A Empennage and not yet started wing kit for sale in San

Ramon, CA. Empennage has no known LCPs and wing has replacement

components from Vans. Price reduced to \$12K OBO for both.



Watch

Nov 9, 2024

#1

ericp

I'm New Here

Attachments

Patron

Home Forum :



Support the definitive community for RV builders and enthusiasts — upgrade your account today!

View upgrades

You get a badge showing your support and some tiers unlock additional features, ad-free viewing, and access to an exclusive forum.

Home

Forums

Main

Classifieds

RV7 Kits 4 Sale

 $\stackrel{ ext{$\triangle$}}{ ext{$\triangle$}}$ FreedomRV8 \cdot $\stackrel{ ext{$\triangle$}}{ ext{$\triangle$}}$ Nov 5, 2024









Watch

Nov 5, 2024

#1

FreedomRV8

I'm New Here

Patron

Report

Empennage and Wing Kits for sale \$15,500. NO laser cut parts. Opened only to inventory. Pick up or will deliver up to 300 miles In original crates. Located Central Arkansas. Jerry Landis. Landis Aviation, LLC Searcy AR. Telephone 501-231-0858 * 501-593-0263

Like

Reply

Home Forum 1



Support the definitive community for RV builders and enthusiasts — upgrade your account today!

View upgrades

You get a badge showing your support and some tiers unlock additional features, ad-free viewing, and access to an exclusive forum.

Home Forums Main Classifieds

RV-9 partial kit for sale - no laser cut parts

 $\stackrel{{\scriptstyle \sim}}{=}$ kjsifer \cdot $\stackrel{{\scriptstyle \circ}}{\bigcirc}$ Dec 3, 2024









Jump to new

Watch

Dec 3, 2024

#1

K

kjsifer I'm New Here

Patron

Cleaning out the hangar. I have too many airplanes and projects. I have decided it may be years before I get to this so decided to go ahead and sell it. This is a partial kit. No laser cut parts! Includes wings partially done and empennage kit, already done. Fuel tanks already done. Includes build manuals and a bunch of extras for building. Asking \$15k or best offer. Looks at Van's website. This would cost you almost 30k if you buy from Van's right now!! I'm

4 0 th 5 4 4 6 8 8	Outlook		Q Search	EG
0	Home View Help			
<i>b</i> *	✓ New mail ✓ ⑩ Delete ✓	☐ Archive		←
ه ق	∨ Folders		$\left(\begin{array}{c} \times \\ \end{array}\right)$ $\left(\begin{array}{c} \times \\ \end{array}\right)$	
4-	■ Inbox	1574		
	CD	4	Van's Aircraft Invitation to Revised Order	
4	Ca Junk Email	4	Portal	- Independent
	Drafts	2		
W	Sent Items		V V: (《)	
χĒ	णि Deleted Items	216		
	☐ Archive	:	Invitation to the Van's	
-	→ Notes		Aircraft Order Portal	
88	CAP		VAN'S AIRCRAFT TOTAL PERFORMANCE	
	Conversation History			
			Dear EDGARDO GOMEZ,	
	∨ Groups		On December 4, 2023, Van's	
	New group		Aircraft filed for protection under Chapter 11 of the federal bankruptcy code, a key step in the reorganization of the company. This action allows Van's to remain open, while making important changes to ensure our future stability and success.	
			At the time of filing for Chapter 11 protection, Van's had hundreds of kit orders	

Please use the link below to create you account and access a website, which will display information about


kit.

which had not yet been delivered. These orders contain terms, conditions, and pricing that Van's cannot perform, and these orders must be modified or

cancelled. You have received this notice because you have at least one order and deposit > PAID IN with us for the purchase of a

7011

Case 23-62260-dwh11 Doc 742 Filed 01/10/25





JACOB DANIELS
Kit Sales, Van's Ai
jake@vansaircraft
-(503) 678-6545 op
www.vansaircraft.c
14401 Keil Road N
Aurora, Oregon 97

This email message is for the sole use of the intended recipient(s) and may contain confidential and privileged information. Any unauthorized review, use, disclosure or



Edgardo Gomez Serial # 83962

This order is under review by our team

X

Request Replacement Laser Cut Parts

Please select a kit below to review the list of laser-cut parts that may have been included in each of your kit(s). You will be able to specify the replacement parts you wish to receive and select a quantity for each part, up to the number that are shipped with that kit.

Van's has placed priority on the manufacturing of parts classified as "Replacement Recommended." These parts will be provided free of charge.

Production of "Acceptable for Use" parts is lower priority relative to those recommended for replacement. As such, they may or may not be available to ship at the same time as the higher-priority parts. "Acceptable for Use" parts are functionally equivalent to CNC punched parts and meet the required specifications for use in the aircraft. The purchase price for these parts equals the current price less a 25% discount, which has already been applied in the prices shown.

Please make your selections and save your requested list of replacement parts. When the parts are in stock, we will reach out to you to confirm your order. Please note that fulfilling replacement parts orders for all customers will take some time. Your patience throughout this process is greatly appreciated.

Select a Kit to Review

	Kit	Parts	Order ID	Status
0	RV-8/8A WING KIT-1	12		Pending
Ö	RV-8 FUSELAGE KIT-1	0		Pending

You are editing your order for RV-8/8A WING KIT-1 Choose another kit

determine parts applicability before requesting replacement components. Some of these notations indicate that Van's Aircraft's Engineering team will be developing an alternative part replacement (additional part(s) that can be added instead of part removal/disassembly). These engineering solutions are currently being developed. Delivery timeframes for these solutions will depend on the complexity of the part(s). We will communicate with applicable customers when

INBD WING RIB SKU: W-710-L Price: \$0.00 Quantity: 0 max: 1 ADD FLAP BRACE SKU: W-721-R Price: \$0.00 Quantity: 0 max: 1 ADD INBD WING RIB SKU: W-710-R Price: \$0.00 Quantity: 0 max: 1 ADD FLAP BRACE SKU: W-721-L Price: \$0.00 Quantity: 0 max: 1	Parts
FLAP BRACE SKU: W-721-R Price: \$0.00 Quantity: O max: 1 ADD INBD WING RIB SKU: W-710-R Price: \$0.00 Quantity: O max: 1 ADD FLAP BRACE SKU: W-721-L Price: \$0.00 Quantity: O max: 1	SKU: W-710-L Price: \$0.00
SKU: W-721-R Price: \$0.00 Quantity: O max: 1 ADD INBD WING RIB SKU: W-710-R Price: \$0.00 Quantity: O max: 1 ADD FLAP BRACE SKU: W-721-L Price: \$0.00 Quantity: O max: 1	ADD
INBD WING RIB SKU: W-710-R Price: \$0.00 Quantity: 0 max: 1 ADD FLAP BRACE SKU: W-721-L Price: \$0.00 Quantity: 0 max: 1	SKU: W-721-R Price: \$0.00
INBD WING RIB SKU: W-710-R Price: \$0.00 Quantity: 0 max: 1 ADD FLAP BRACE SKU: W-721-L Price: \$0.00 Quantity: 0 max: 1	Quantity: 0 max: 1
SKU: W-710-R Price: \$0.00 Quantity: 0 max: 1 ADD FLAP BRACE SKU: W-721-L Price: \$0.00 Quantity: 0 max: 1	ADD
SKU: W-721-L Price: \$0.00 Quantity: 0 max: 1	SKU: W-710-R Price: \$0.00 Quantity: 0 max: 1
	SKU: W-721-L Price: \$0.00

options become available.

| ドルバーン イル・とし・イフ Case 23-62260-dWh11/ Doc 742 Filed 01/10/25

than any edge. This is true of both punched and laser-cut parts, resulting in an assembly that has the same susceptibility to fatigue.

Q: Alternate solutions have been proposed in place of part replacement, when will those be available and what locations? In what order are they being completed?

Alternate solutions are being developed for difficult-to-replace components, and are prioritized by the largest number of kits affected. This has focused our initial effort on the RV-10 and RV-14.

Wings, ailerons, and flaps will require the replacement of Redlabelled/classified components, no alternative solutions will be developed. Service information will be released that provides instructions for replacement and the initial timeline for replacement. This documentation is not required to replace these components, builders can proceed with replacement at their discretion.

There is no alternative being developed for Yellow-labelled components that support boarding step loads, these are the parts located in the baggage area on numerous aircraft. Builders should continue to inspect these areas over time.

All alternative solutions are developed to:

- Reduce stresses
- Reduce rivet loads
- Provide redundant load paths

These will increase the fatigue life of the components to be as good or better than the punched equivalent.

Alternate Solutions:



14401 Keil Road NE, Aurora, Oregon, USA 97002 PHONE 503-678-6545 • FAX 503-678-6560 www.vansaircraft.com • info@vansaircraft.com

SERVICE LETTER 00091 - REV 1

Date Released:

November 11th, 2023 (REV 1)

Date Effective:

November 9th, 2023

Subject:

Laser Cut Parts and Certification of Aircraft

Affected Models:

All RV models with installed laser cut parts classified as

"replacement recommended"

See VAD-10041 Laser Cut Parts List

Required Action:

Inspection of parts labelled "replacement recommended"

until further update

Time of Compliance:

See the Synopsis section below

Supersedes Notice:

None

Labor Required / SLSA Warranty Allowance: None at this time

Level of Certification:

SLSA: LSA Repairman Maintenance or A&P

ELSA: Owner (certification not required)

Check the rules of the local controlling authority/agency and the operating

limitations for your aircraft.

Synopsis:

The FAA issued an email notification to its inspectors related to certification of RV aircraft containing laser cut parts in "critical structures." These parts are classified as "replacement recommended" in the Laser Cut Parts List (VAD-10041) as published by Van's Aircraft. Laser cut parts were produced for Van's Aircraft by an outside supplier from January 2022 to June 2023. All testing to date has shown that there is no immediate airworthiness concern for aircraft with laser cut parts. In addition, there is no immediate need to replace laser cut parts that are already installed in an aircraft prior to inspection for certification. Van's Aircraft has conducted an analysis of the airworthiness and service life of these parts. A summary of this investigation, "Laser-Cut Parts Engineering Evaluation," is available on the Van's Aircraft website.

Van's Aircraft is in the process of planning its parts replacement program and will release further information regarding the method and time of compliance for inspection, repair or replacement of laser cut parts.

Aircraft with "replacement recommended" laser cut parts may continue to be certified and operated.

14401 Keil Road NE, Aurora, Oregon, USA 97002 PHONE 503-678-6545 • FAX 503-678-6560 www.vansaircraft.com • info@vansaircraft.com

Laser-Cut Parts Engineering Evaluation

September 24, 2023

Introduction

Following reports from the field of irregular holes and cracked dimples in laser-cut sheet metal parts, an investigation was conducted to review the prevalence of these defects and the effect they have on the structure of aircraft parts and assemblies. The service-life of laser-cut structures has been evaluated through conservative analysis, computer simulations and mechanical testing of representative structural joints, sub-assembly details, and full assemblies. Based on the results of analysis and testing, Van's Aircraft has classified each part that was manufactured via the laser-cutting process into two categories: Parts that are Recommended for Replacement and parts that are Acceptable for Use. These classifications have been made out of an abundance of caution, and all parts classified as Acceptable for Use are functionally equivalent to punched parts.


From January 2022 through June 2023, Van's had certain parts manufactured using a lasercutting process. These parts make up a portion of the internal structure, made of .040" aluminum or thinner, primarily; ribs, frames, and bulkheads. Note that skins, wing spars, and wing spar doublers were never produced using laser cutting. Rather, those parts were, and are, produced using the CNC punching or CNC machining processes that Van's has employed for many years.

Stress and Fatigue Life

The primary concern related to irregular holes and/or cracked dimples is what effect these have -> SUCH AS RIVE!

Fatigue is a phenomenon that affects all aluminum structures, regardless of stress level. Any REPLACE A PART amount of load applied to aluminum a sufficient number of times will eventually result in crack. Fatique life is finite, and a small portion of that part's life is used during every loading cycle, and is directly related to the magnitude of the stress developed. In any particular part the nonuniform application of load, the detailed design characteristics, and the nature of how that load is reacted will result in dramatically varied stresses. The point of highest stress will be the location where the fatigue life will be exhausted first, resulting in a fatigue crack.

In round numbers, a given reduction in stress increases the service life of a part exponentially; to the power of four. For example, for each 50% reduction in stress, the predicted service life of a part increases 16 times. The graph below illustrates this concept.



Case 23-62260-dwh11 Doc 742 Filed 01/10/25



- o Dimpled holes
- o Machine-countersunk holes
- o Non-dimpled holes
- Nested dimpled/countersunk holes
- Double-shear joints
- Non-reversing loads
- Reversing loads
- Combined shear and tension loads

Test samples were designed to highlight the worst-case fatigue properties for the laser-cut holes. Each sample contained multiple fasteners, and the failure of any hole would conclude the test. For example, a double-shear rivet test sample contains 8 rivets and is simultaneously testing 16 laser-cut holes. This conservatively establishes a sample life that is based on the worst of the group.

This partner company also provided detailed assessment of the metallurgy surrounding the laser-cut edges of dimpled and un-dimpled fastener holes.

Airframe Service Life Analysis

While analyzing the service life of an aircraft, criticality of the structure, stress levels, and the expected loading cycles were determined.

Structural assemblies were analyzed and classified as Primary Structure and Secondary Structure based on their application, relationship to flight loads, and criticality to the safe operation of the aircraft. Primary Structure is essential in maintaining the overall structural integrity of the airplane.

To identify high-stress locations and highly-loaded fastener holes, Van's Aircraft performed traditional mathematical analysis and computer simulations using Finite Element Analysis (FEA). This was done at the major assembly scale and refined to the smallest details. When analyzing stress levels, features such as relief notches between formed rib flanges typically exhibited the highest levels of stress, much greater than stresses observed at the fastener holes. Of note, fleet history has not indicated fatigue cracking occurs at these locations.

Many parts serve their function at stresses and loads far below that which would make them susceptible to fatigue damage. These are cases where the parts do not directly resist major portions of flight or ground loads and are often functioning to stabilize Primary Structure (typically the skins and spars of the airframe). This stabilizing structure is used to maintain shape and prevent buckling of another part, which increases that primary component's ability to resist compression or shear loads. At the mild stresses developed in these stabilizing parts, the laser-cut components are functionally equivalent to punched components, both have an unreasonably remote possibility of ever developing fatigue cracking in service.

To conservatively estimate the rate at which an aircraft would use the fatigue life of its most highly loaded components, an extreme use case was selected. Well beyond what is reasonable, and far beyond any known to Van's Aircraft, this was a theoretical aircraft spending 50% of flight time in flight-school operations, and 50% of flight time performing constant aerobatic maneuvers up to the design limits of the aircraft. This loading spectrum (load intensities and load cycle rates) was developed from real-world data (a survey of multiple RV's used in aerobatic airshow routines). The resulting aircraft model assumes a reduction of fatigue life at a rate more than 25 times that of an aircraft used in flight-school conditions alone.

Using this conservative aircraft model, an assessment was then made to determine at what stress level structures became susceptible to fatigue damage using the identified loading spectrum. Each part was then classified as needing replacement or acceptable for use.

Had we used a less conservative estimate of the loading spectrum closer to real-world use, the result would have been a dramatically longer life, proportional to the realistic use of the airplane. A review of a single flight where aerobatics are performed will typically include less than 10



All customers, building or flying, should plan to replace the components marked for replacement in the laser-cut part list, or install additional parts developed by Van's as alternatives to replacement. In some instances, the Van's Engineering team will develop alternate solutions that may be installed instead of a complete part replacement. These alternate solutions will reduce workload significantly while also addressing any potential issues.

For flying aircraft, Van's Aircraft will provide further guidance including a time limit for part replacement after further testing and analysis has been conducted.

Quickbuild Kits

Several customers are waiting to receive quick build kits. Some of those kits are located in the Van's Aircraft warehouse and others are still in transit from our quick build assembly facilities. We intend to update these kits before shipment to the customer. This will involve replacing the parts that are recommended for replacement and/or installing alternate engineering solutions. The large number of kits to be reworked, combined with limited manpower, will result in extended lead-times. In addition, we are pursuing alternate resources to rework kits to help reduce lead times. This process will take time and we will communicate updates to quickbuild customers.

Many quick build kits require limited rework and a small number of parts that will need to be updated. If desired by the customer, to reduce lead time Van's will deliver those kits requiring limited rework to a customer along with the punched replacement parts. In instances where parts are complex to replace, the preferred solution will be to install parts developed to simplify and reduce the level of disassembly necessary. Please review the laser-cut parts list and your kit to become familiar with how involved a repair may be.

RV-12 Update

Fatigue testing has shown a lifespan of RV-12 parts that is significantly beyond the expected life of an airplane. A full aircraft sub-assembly with laser-cut components was tested through an accelerated life test representative of 30,000 hours of flight training use. This test was concluded with no deformation, failure, or detectable change to the assembly.

Accelerated life testing using representative samples, of various configurations, has shown a very long service life can be expected. This testing of highly-loaded rivets demonstrates that the rivet will fatigue before the hole, regardless of whether the fastener hole was punched or laser-cut. Lightly-loaded fastener holes will fatigue before the rivet, but have a dramatically longer fatigue life that is many multiples of the life of an aircraft. For these reasons, we determined that there is more than sufficient life for RV-12 aircraft utilizing laser-cut parts.

We have evaluated and classified the laser-cut components of the RV-12, and out of an abundance of caution we recommend the replacement of the following trim system components: F-1211D, F-1287A-1, F-1287D, and HS-1220. Service information along with a life limit for these parts will be forthcoming. For now, you may continue to fly your aircraft. The Laser Cut Parts List has been updated to include these RV-12 parts.

Summarv

To reiterate, laser-cut parts have been classified using conservative assumptions and with an abundance of caution. Once the parts that Van's has recommended for replacement are addressed, the remaining laser-cut parts are secondary structure or lower, are functionally equivalent to punched parts, and are acceptable for use.

The analysis of fatigue life in these remaining parts is based on peak stress, from test data that uses worst-case outliers and statistical offsets. The calculated expected life is much greater.

It is very unlikely a fatigue crack should ever develop. However, should that happen RV structure will allow for ample time to inspect and correct. This will not alter the useful life of the aircraft.